

Fig. 1 is a cross-sectional view of a mechanical assembly. A central shaft (1) passes through a housing (2). The housing has sections labeled 2(b), 2(f), 2(c), and 2(g). A bracket (5) indicates a distance between two points on the shaft. Other labels include 3, 4, 6, 7, 8, 9, K, L, and A.

FIG. 3




FIG. 4




FIG. 5

